



Manhole 19EP-6 looking
South towards Manhole
20EP-15

The 3 cables in right
conduit and 1 large cable in
left duct are cut loose in
Manhole 20EP-15


Manhole 19EP-6 looking South towards Manhole 20EP-15



Manhole 19EP-6 looking toward to Manhole 20EP-15



Manhole 20EP-14 looking toward to Manhole 20EP-15



Manhole 20EP-15 looking toward to Manhole 20EP-14